WIRING INSTRUCTIONS

TITLE


ORBITAL SANDERS

MILWAUKEE ELECTRIC TOOL CORP.

13135 WEST LISBON RD. BROOKFIELD, WIS

Date Nov.'69

BULLETIN 58-01-0470



NOTE:
ALL LEADS MUST BE HELD TO ± 1/8"
ALL FIELD LEADS TO BE MEASURED FROM
AND PERPENDICULAR TO LAMINATIONS.
ALL LEAD LENGTHS ARE BEFORE STRIPPING.

WHERE TERMINAL AND CONNECTOR COMBINATIONS ARE SPECIFIED, SEE ELECTRICAL PARTS CHART FOR PART NO. AND QUANTITY AND DRAWING FOR ACTUAL HOOK-UP

WIRING SPECIFICATIONS											╛											
Wire	Wire		Lgth.	Terminal			Connector			Wire	Wire	Ga.	Lgth.	Terminal			Connector					
Color	No.	Ga.	in.	T1	T2	Т3	T4	C1 C2	C3	C4	Color	No.	Ga.	in.	T1	T2	T3	T4	C1	C2	C3C	4
Red	ı	Fld.	2-3/4							Ì	Black	7	Cord	2)			x		-	
Brown	2	Fld.	5					x		Ì	White	8	Cord	2					×			
}											Green	9	Cord	2	Х					į	İ	
Black	3	Swit.	2-5/8							1									ŀj		i	
Black	4	Swit.	2-5/8											İ								-
Black	5	Swit.	1-3/4								<u> </u>			!								
Black	6	Swit.	1-3/4																		Ĺ	╛

										
Electrical Parts										
TERMINAL DESCRIPTION										
Code	ode Part No.									
Τl	23-74-0050	1								
CO	CONNECTOR DESCRIPTION									
Code	Part No.	Qnty.								
C1	23-74-0080	3								
SWITCH DESCRIPTION										
Code	Part No.	Qnty.								
\$1	23-66-0380	1								

Form OE-24